



| | |
|---|--|
| SITE NAME: | David John Property |
| SITE NUMBER: | 0000126 |
| ADDRESS: | South end of Vandalia Street on commercial lot |
| CITY: | Otterbein |
| COUNTY: | Benton |
| SCORE: | 43.08 |
| SCORE DATE: | August 28, 2001 |
| CONTAMINANT TYPE: | Spent Solvents and Paint Residue |
| MEDIA AFFECTED: | Soil and Groundwater |
| CONTACT PERSON: | Aaron Green at (317) 234-0350 |
| LAST REVISED: | October 2001 |
| SITE PHOTO | |
| <p>STATUS:</p> <p>The property owner, Mr. David John, operated a drum recycling operation at the site for approximately 20 years. On December 1, 2000, while conducted a spill incident investigation, IDEM discovered between 30 to 40 empty drums and soils discolored by paint sludge through out the property. During the incident investigation, Mr. John acknowledged that the residual fluids contained in the drums were dumped onto the ground. On December 5, 2000, a remedial investigation was conducted and revealed elevated concentrations of volatile organic compounds in both the subsurface soils and groundwater beneath the property. Remedial actions are ongoing.</p> | |